

Amendments to the Specification:

Please amend the specification as follows:

Please replace amended paragraph number [0033] with the following rewritten paragraph:

One end of the wire 12 passes through the piston portion 24a and the rod 24b and is connected to the side of the [[rob]] rod 24b opposite the piston portion 24a. The wire 12 passes from the piston 24 through the aforementioned wire through hole formed on the curved portion 20a of the pipe 20 in an airtight and slidable manner and extends externally from the cylinder 21 in the upper left diagonal direction, and further is bent by the collar 19 attached to the bracket 10 so that the direction thereof is changed in that of the connector assembly 14.